## FIELD INSPECTION REPORT

Date of Inspection:	10/12/20	District: S-	American de la companya de la compan
Division: Semastifu		Length (km):	
Name of the Road:	Zero mile	to Dazasi nia Mal 11	+ = 1
Scheme/Programme:	MAINTENANCE	in mana date	7 704
Package No.:		Road Id No.:	
tatus of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity	/Up gradation/ Maintenance	
Sl. No.		o be checked	Remarks
1. Pavement	The state of the s		acemarks
a) Road Junction condition			e indianali, in
	Condition of Surfacing		
c) Riding Quality	Riding Quality		
d) Road Camber	Road Camber		
e) Whether free aggregates in c	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f) Contraction Joi	Contraction Joints provided or not (CC Pavement)		
g) Compaction of	Compaction of flank/slope & raincuts if any		
2. Cross Drainag	e = 1		
Condition of her	Condition of head walls in Hume pipe culverts including its painting		
Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c) Condition of rail	Condition of railings/slab/approach for Bridges		
. Road Furniture	The second		
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
Compliance His	iory		
Status of ATR's	& any others		legg.

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

**a**.e\_

NB

(Signature)

Gentom Dow

NAME: