


FIELD INSPECTION REPORT

Date of Inspection: 09/12/2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 6.80
Name of Road : NH-28 Shankar Chowk Se Chhapra Nitya Nitya Dalia Baste		
Scheme / Programme: MAINTENANCE		MR New
Package No:		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance

Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	—
f)	Constraction Joint provided or not(CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	—
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridge	—
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement(SRI)	—
Unsatisfactory(U)	—


 (Signature) 09/12/20

NAME: Mananjoy Kumar
 DESIGNATION: AE