


FIELD INSPECTION REPORT

Date of Inspection:	10/12/2020		District: Samastipur
Division: RWD Dalsinghsarai			Length(km): 2.600/km
Name of Road :	patel chowk Gagan Shami house to megli karpuri Bandhitala		
Scheme / Programme:	MAINTENANCE MR NEW 2018		
Package No:			
Status of the Project:	Ongoing/Completed/Under Maintenance ongoing		
Work is a case of:	New Connectivity/ Up gradation/ Maintenance up gradation		
Sl. No	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction Condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	-	
f)	Constraction Joint provided or not(CC Pavement)	-	
g)	Compaction of flank/slope & raincuts if any	S	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	N.A	
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	N.A	
c)	Condition of railings/slab/approach for Bridge	N.A	
3	Road Furniture		
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	main board fixed	
4	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement(SRI)	-
Unsatisfactory(U)	-


10/12/2020
(Signature)

NAME: Anil Prasad
DESIGNATION: JS