

FIELD INSPECTION REPORT


| | | |
|---|--|--|
| Date of Inspection: 9/12/2020 | | District: Samastipur |
| Division: RWD Dalsinghsarai | | Length(km): |
| Name of Road : Vidyasagar Parvati Gumbh 44 to Dhamma Parvati Ex. S. 12. | | |
| Scheme / Programme: MAINTENANCE New MP 18 | | |
| Package No: | | Road Id No: |
| Status of the Project: Ongoing/Completed/Under Maintenance ongoing | | |
| Work is a case of: | | New Connectivity/ Up gradation/ Maintenance up gradation |

| Sl. No | Parameters to be Checked | Remarks |
|----------|--|-------------------|
| 1 | Pavement | |
| a) | Road Junction Condition | — |
| b) | Condition of Surfacing | — |
| c) | Riding Quality | — |
| d) | Road Camber | — |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement | — |
| f) | Constraction Joint provided or not(CC Pavement) | — |
| g) | Compaction of flank/slope & raincuts if any | — |
| 2 | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | — |
| b) | Condition of Abutment & Wing walls , Slab in RCC culverts | — |
| c) | Condition of railings/slab/approach for Bridge | — |
| 3 | Road Furniture | |
| a) | Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | main board fixed. |
| 4 | Compliance History | |
| a) | Status of ATR's & any others | |

Slip dated date of completion is 16.9.2020 but till now AT Smtu work not started.

Overall Rating :

| | |
|--|-----|
| Satisfactory(S) | |
| Satisfactory but requires Improvement(SRI) | SRI |
| Unsatisfactory(U) | |


 9/12/2020
 (Signature)

NAME: Anil Kumar
 DESIGNATION : OB