

# FIELD INSPECTION REPORT

| Date of Inspection:  |  | District: Samastipur                          |
|--|--|---|
| Division: RWD Dalsinghsarai  |  | Length(km): 1.95 km                           |
| Name of Road : TO 2 Harsingpur panchayat bhatua gate                           |  |   |
| Scheme / Programme: MAINTENANCE - MR old.                                      |  |   |
| Package No:  |  | Road Id No:                                   |
| Status of the Project: Ongoing/Completed/Under Maintenance - under maintenance |  |   |
| Work is a case of:   |  | New Connectivity/ Up gradation/ Maintenance ✓ |
| Sl. No   | Parameters to be Checked   | Remarks                                       |
| <b>1</b>   | <b>Pavement</b>  |   |
| a)   | Road Junction Condition  | S   |
| b)   | Condition of Surfacing   | SPI   |
| c)   | Riding Quality   | -   |
| d)   | Road Camber  | S   |
| e)   | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement                          | -   |
| f)   | Constraction Joint provided or not(CC Pavement)  | -   |
| g)   | Compaction of flank/slope & raincuts if any  | SPI   |
| <b>2</b>   | <b>Cross Drainage</b>  |   |
| a)   | Condition of head walls in Hume pipe culverts including its painting   | re. A   |
| b)   | Condition of Abutment & Wing walls , Slab in RCC culverts  | -   |
| c)   | Condition of railings/slab/approach for Bridge   | -   |
| <b>3</b>   | <b>Road Furniture</b>  |   |
| a)   | Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | S   |
| <b>4</b>   | <b>Compliance History</b>  |   |
| a)   | Status of ATR's & any others   | NO  |


Overall Rating :

|  |     |
|--|-----|
| Satisfactory(S)                            |     |
| Satisfactory but requires Improvement(SRI) | SPI |
| Unsatisfactory(U)                          |     |

NAME:

DESIGNATION :

Anil Kumar  
DO

  
 (Signature)