

FIELD INSPECTION REPORT

Date of Inspection : 07.12.2020	District: Begusaraj
Division : Teshra	Length (km): 5.050 km
Name of the Road: 134 - Rudauli - Chauhan to Bhaerul	
Scheme/Programme: MAINTENANCE	
Package No.: RM/BEM/TEB/19/0002	Road Id No.: 32010502052
Status of the Project: Ongoing/Completed/Under Maintenance - w	
Work is a case of: New Connectivity/Up gradation/ Maintenance - w	Agreement/Policy

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Till date Agreements has been not done by contractor
 G. S. D. S. D.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Umesh Kr Mahesh
 DESIGNATION: Junior Engineer

(Signature)