

FIELD INSPECTION REPORT

Date of Inspection :	10/12/2020	Location:	Bogusareu
Division :	Balia	Length (km):	2.330
Name of the Road:	NH-31 Jafmagan Dheula to Awadh Tirkul Road.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	32010601030
Status of the Project:	Ongoing/Completed/Under Maintenance / N/A		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameter to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincut if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in flume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slope & CC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any other	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

DESIGNATION:

[Signature]
10/12/2020

[Signature]
11.12.20
(Signature)
Executive Engineer
RWD Works Division, Balia