

FIELD INSPECTION REPORT

(Block - Jagdichpur)

Date of Inspection : 04-12-2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 2.10 Km.	
Name of the Road : Repair of Road from Salempur Mod to Salempur village			
Scheme / Programme : MAINTENANCE (old MR)			
Package No. :		Road Id No. : 20703208222	
Status of the Project : Ongoing / Completed / Under Maintenance			
Work is a case of : New Connectivity / Up gradation / Maintenance			
S/L No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S / U	U
b)	Condition of Surfacing	S / U	U
c)	Riding Quality	S / U	U
d)	Road Camber	S / U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	} NA
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	
g)	Compaction of flank/slope & raincuts if any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	} NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	Yes
4.	Compliance History		
a)	Status of ATR's & any others	NO	
Overall Rating :			
Satisfactory (S)		-	
Satisfactory but requires Improvement (SRI)		-	
Unsatisfactory (U)		U	

NAME: Radda Raman Sify
DESIGNATION: Assistant Engineer

04/12/20
J-E

(Signature)

04/12/20
AR