

FIELD INSPECTION REPORT

Date of Inspection:	District: <u>Palwal</u>
Division: <u>Palwal</u>	Length (km): <u>0.500</u>
Name of the Road: <u>Restoration of the pucca road from Gullu Bazar to Sahaypur</u>	
Scheme/Programme:	<u>MAINTENANCE</u>
Package No.:	Road Id No.:
Status of the Project:	<u>Ongoing/Completed/Under Maintenance</u>
Work is a case of:	<u>New Connectivity/Up gradation/ Maintenance</u>

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Rolling Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board/km & 200m cones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note: - the road has been transferred to Reg

[Signature]
11/12/24
AE

[Signature]
11/12/24
AE

[Signature]
(Signature)