FIELD INSPECTION REPORT

Date of 1	nspection: 03.12.2020 District: Patna	
Division: Patra Length (km): 2.100		and the second s
Name of	the Road: Fatura Islamfus to Jagraebad.	
Scheme/	Programme: MAINTENANCE	
Package	No.: MR-N/201920/Patra/02 Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (5)	ot done
Satisfactory (S) Satisfactory but requires Improvement (SRI)	NA
Unsatisfactory (U)	

NAME: Himanshu Roy DESIGNATION: Assistant Engineer