

# FIELD INSPECTION REPORT

Date of Inspection :	11-12-2020	District : BHAGALPUR
Division :	NAUGACHHIA	Length (km) : 2.500
Name of the Road :	RCD Road No 14 to GosaiGaon Ray Baba Asthan via Dandam yadav Mukhya house	
Scheme/Programme :	Maintenance	
Package No. :		Road Id No. : 20703300815
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameteres to be cheeked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Road Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Conpaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culvert including its painting.	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Cross Drainage	
a)	Whether sign boards/informatory/cautionaty Boards/ km & 200m stones/Pavements roads marking are provided and maintained.	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)


Unsatisfactory (U)

For Revise AA DPR Submitted to Engineer in chief Table vide CE 2 Letter No 2131 dated 21-05-2020 due to 1.500 Km Remaining Length

NAME : ANIL KUMAR

DESIGNATION : ASSISTANT ENGINEER

R.W.D. works Sub-division  
Gopals

  
11-12-2020  
(Signature)