

FIELD INSPECTION REPORT

Date of Inspection :	05/12/2020	District:	Bhopure, Ara.
Division :	RWD, Div. Jagdishpur	Length (km):	0.50 Km.
Name of the Road:	Repair of road from NH-84 Situated Kalyanpur R.E. Road.		
Scheme/Programme:	MAINTENANCE Merged into NH-84 Amara Nawada to Kalyanpur Bazar		
Package No.:	Belharia ID-10401708060;	Road Id No.:	10401708052
Status of the Project:	Ongoing/Completed/Under Maintenance NA		
Work is a case of:	New Connectivity/Up gradation/ Maintenance NA		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U — NA.
b)	Condition of Surfacing	S/U — NA.
c)	Riding Quality	S/U — NA.
d)	Road Camber	S/U — NA.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No — NA.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No — NA.
g)	Compaction of flank/slope & raincuts if any	Yes/No — NA.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U — NA.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U — NA.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U — NA.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No — NA.
4.	Compliance History	
a)	Status of ATR's & any others	NA.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NA

NAME: Gayanand Misra

05/12/2020
(Signature)