

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020	District: Buxar
Division : Dumaradn	Length (km): 1.750
Name of the Road: Brahmpur Petrol Pump to Patasia	
Scheme/Programme: MAINTENANCE	New maintenance Policy
Package No.: MR-N/19-20	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	On Going
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N.A.
b)	Condition of Surfacing	S/U N.A.
c)	Riding Quality	S/U N.A.
d)	Road Camber	S/U N.A.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A.
g)	Compaction of flank/slope & raincuts if any	Yes/No N.A.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N.A.
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	just started
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

31/12/20
J.E.

(Signature)

NAME:

REDMI NOTE 6 PRO
MI DUAL CAMERA