

# FIELD INSPECTION REPORT

Date of Inspection :	9.12.20	District:	Duxar
Division :	Duxar	Length (km):	3.01 km
Name of the Road:	Chausa Line Nahar to Lalachak Shivmukhi Pk		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-20 Duxar/25	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <i>Ongoing</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	<b>Pavement</b>		
a)	Road Junction condition	N/A	S/U
b)	Condition of Surfacing	N/A	S/U
c)	Riding Quality	N/A	S/U
d)	Road Camber	N/A	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A	Yes/No
g)	Compaction of flank/slope & raincuts if any	N/A	Yes/No
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N/A
3.	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	N/A
<b>Compliance History</b>			
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

N. K. Himachal

DESIGNATION:

AE RWD R&P

(Signature)

AE RWD R&P

Scanned with CamScanner

Scanned with CamScanner