

FIELD INSPECTION REPORT

Date of Inspection :	9-12-2020	District:	Buxar
Division :	Buxar	Length (km):	2.042 Km
Name of the Road:	Basahi-Sikahi to Rasen Khura		
Scheme/Programme:	MAINTENANCE MR/3054 new aram fairance policy 2018		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ongoing		
Work is a case of:	New Connectivity/Up gradation/ Maintenance upgradation		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	NA S/U
b)	Condition of Surfacing	NA S/U
c)	Riding Quality	NA S/U
d)	Road Camber	NA S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	NA Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Mubarak Hussain Ansari

NAME:

ds
9.12.20
AL

[Signature]
9-12-2020
(Signature)

R.W.D. works section
Raipur