


FIELD INSPECTION REPORT

Date of Inspection :	10/12/2020	District :	Bhagalpur
Division :	RWD(W) Div. Nangachhla	Length (km) :	0.810 km
Name of the Road :	Road No. 14- Gayatri Mandir to Bihpur		
Scheme/Programme :	Maintenance New Maintenance Policy 2018		
Package No. :		Road Id No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Road Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culvert including its painting.	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Cross Drainage		
a)	Whether sign boards/informatory/cautionary Boards/ km & 200m stones/Pavements roads marking are provided and maintained.	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note - Financial Bid forwarded to SE, RWD(W)
Circle Bhagalpur vide letter no. 1522
dt - 05/12/2020


10/12/2020
(Signature)

NAME : VIKASH KUMAR
DESIGNATION : Junior Engineer
RWD, Work Section
Bihpur