

FIELD INSPECTION REPORT

Date of Inspection :	10-12-2020	District :	Bhagalpur
Division :	NAUGACHHIA	Length (km) :	1.200
Name of the Road :	M/R to ROAD from BIKRAMSILA setu APPROACH ROAD		
Scheme/Programme :	Maintenance GOSAIYACHAK PWD ROAD to PARBATHA DURGASTHAN		
Package No. :		Road Id No. :	20703308054
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Road Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culvert including its painting.	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Cross Drainage		
a)	Whether sign boards/informatory/cautionary Boards/ km & 200m stones/Pavements roads marking are provided and maintained.	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Work already completed by LAED Nangachhia
approx. six months before.

[Signature]
(Signature) 10/12/20

NAME : *Brijesh Kumar Singh*
DESIGNATION : *Junior engineer*