

FIELD INSPECTION REPORT

Date of Inspection :	07-12-2020	District : BHAGALPUR.
Division :	NAUGACHIA	Length (km) : 3.190 Km.
Name of the Road :	MIRAJ R.E.D. ROAD NANKAR TO NAGARTOLI VIA BAHATRA.	
Scheme/Programme :	Maintenance	Road Id No. : 20703308058
Package No. :		
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked	Remarks
1	Pavement	S/U
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Road Quality	S/U
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	S/SRI/U
a)	Condition of head walls in Hume pipe culvert including its painting.	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Cross Drainage	
a)	Whether sign boards/informatory/cautionary Boards/ km & 200m stones/Pavements roads marking are provided and maintained.	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Surface Damage. D.P.R. for Administrative
Approval sent to Head Quarter vide S.E.
R.W.D. work circle Bhagalpur letter NO
1270 dated 13-11-2019.


07-12-2020
(Signature)

NAME: ANIL KUMAR

DESIGNATION: ASSISTANT ENGINEER
R.W.D. WORKS SUBDIVISION KHARJK