

FIELD INSPECTION REPORT

Date of Inspection:	District: Samastipur
Division: RWD Dalsinghsarai	Length(km): 3.802 km

Name of Road: M P R to Mahishari Upiyarpur

Scheme / Programme: MAINTENANCE - M P Year 2018

Package No: Road Id No:

Status of the Project: Ongoing/Completed/Under Maintenance - ongoing

Work is a case of: New Connectivity/ Up gradation/ Maintenance up gradation

Sl. No	Parameters to be Checked	Remarks
1	Pavement BT Work and standards	
a)	Road Junction Condition	✓
b)	Condition of Surfacing	
c)	Riding Quality	—
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓
f)	Construction Joint provided or not(CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	—
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	✓
c)	Condition of railings/slab/approach for Bridge	—
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	—
4	Compliance History	
a)	Status of ATR's & any others	

Stipulated date of agreement is 19.11.20 but till now BT work not started.

Overall Rating :

Satisfactory(S)	—
Satisfactory but requires Improvement(SRI)	—
Unsatisfactory(U)	U

Contractor delayed for delay in work

10/12/2018
(Signature)

NAME: Manoj Kumar
DESIGNATION : AE