


FIELD INSPECTION REPORT

Date of Inspection :- 7.12.20		District :- Khajana
Division :- Khajana		Length (Km) :- 1.170
Name of Road :- Khajana - Gauri PWD Road perched at Chauri Bhadas PMGSY road.		
Scheme/Programme :- New - MR		Maintenance
Package No. :-		Road ID No. :-
Status of Project :- CC work completed		Ongoing/Complete/Under Maintenance
Work is a case of :- BT in progress		New Connectivity/Upgradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	S/S/U
b)	Condition of Surface	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Construction Joints provided or not (CC Pavement)	✓ Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)


 7.12.20
 SE/ Khajana