

FIELD INSPECTION REPORT

Date of Inspection :	09/12/2020	District:	
Division :	WORK DIVN DHAKA	Length (km):	2.10 km
Name of the Road:	Chiraiya Purnahiya RD road to Mohaddipur		
Scheme/Programme:	MAINTENANCE	(New Maintenance Policy)	
Package No.:		Road Id No.:	NEA 22000188
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		S/U
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

N.A

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work not started by Agency (contractor)

NAME:

Ramchandra Daswan

DESIGNATION:

Executive Engineer

(Signature)

BE

09/12/20
JE