

**FIELD INSPECTION REPORT**

Date of Inspection : 09.12.20	District: Muzaffarpur
Division : R.W.D Muz. West	Length (km): 4.0
Name of the Road: Rampur Bheriyahi - Chandpura Path	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	In progress - S/U
b)	Condition of Surfacing	dw S/U
c)	Riding Quality	dw S/U
d)	Road Camber	dw - S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	C.C.P. No provision Yes/No
f)	Contraction Joints provided or not (CC Pavement)	No provision Yes/No
g)	Compaction of flank/slope & raintcuts if any	In progress Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	dw S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	dw S/SRI/U
c)	Condition of railings/slab/approach for Bridges	dw S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	—

Overall Rating :	Satisfactory (S)	5
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

*J. M. 09.12.20*

(Signature)

NAME:

DESIGNATION: