

FIELD INSPECTION REPORT

Date of Inspection:	19/07/2020	District: Nagpur/Deoghat
Division:	E-W & N-S	Length (km):
Name of the Road:	Shivaji Marg, Nagpur	Line - East of Simra Ghat, Deoghat
Scheme/Programme:	MAINTENANCE	
Package No.:	RM/NU/HW/19/07/20	Road Id No. 411 - 2200046412
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross-Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

7-12-20
(Signature)

NAME: Satya Nalayou patwari

DESIGNATION: T-E patwari