

FIELD INSPECTION REPORT

Date of Inspection :	11-12-2020	District : BHAGALPUR
Division :	NAUGACHHIA	Length (km) : 2.450
Name of the Road :	NANHKAR TO BIRBANNA VILLAGE	
Scheme/Programme :	Maintenance	
Package No. :		Road Id No. :
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameteres to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Road Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culvert including its painting.	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Cross Drainage	
a)	Whether sign boards/infomatory/cautionaty Boards/ km & 200m stones/Pavements roads marking are provided and maintained.	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Financial Bid forwarded to S.E. R.W.D.
WORKS circle Bhagalpur vide letter no
1531 dt 08-12-2020.

NAME : RAMASHISH PRASAD
DESIGNATION : EXECUTIVE ENGINEER

(Signature)

RAMASHISH
11/12/20

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल नवगांधीया