

# FIELD INSPECTION REPORT


Date of Inspection : 7/12/20		District: Sumantipur
Division : Sumantipur		Length (km): 1.45
Name of the Road: SH to Lachbarampur		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: HEA22000572
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	~S/U
b)	Condition of Surfacing	~S/U
c)	Riding Quality	~S/U
d)	Road Camber	~S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	~S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	~S/SRI/U
c)	Condition of railings/slab/approach for Bridges	~S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	.
Unsatisfactory (U)	

NAME:

Gautam Das  
2.E.

  
7/12/20  
(Signature)