

FIELD INSPECTION REPORT		
Date of Inspection-	10-12-2020	District Arraria
Division-	Farbisganj	Length (KM) 0.743 km
Name of Road-	Kirkichiya to Aadibesi Tola	
Scheme/Programme-	Maintenance ✓	
Package no.-	MMGSY	Road Id No.
Status of the Project	On going/Complete/Under Maintenance ✓	
Work is a case of	New Connectivity/Up gradation/Maintenance ✓	
sl no.	Parameters to be Checked	Remarks
<b>1</b>	<b>Pavement</b>	
a	Road Junction Condition	S/U ✓
b	Condition of Surfacing	S/U
c	Riding Quantity	S/U
d	Road Camber	S/U
e	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No ✓
f	Contraction joints provided or not (CC Pavement)	Yes/No ✓
g	Compaction of flank/slope & raincuts if any	Yes/No ✓
<b>2</b>	<b>Cross Drainage</b>	
a	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b	Condition of Abutment & Wing walls, Slab in RCC Culverts	✓S/SRI/U
c	Condition of railings/slab/approach for Bridges	S/SRI/U NA
<b>3</b>	<b>Road Furniture</b>	
a	Whether sign board/informatory/cautionary Board/KM & 200 m stones/Pavement road markings are provided and maintained	Yes/No ✓
<b>4</b>	<b>Compliance History</b>	
a	Status of ATR's & any others	

Overall Rating:

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

Ant 10.12.20

Signature  
C.E-2

Name

U. Yogeshwar Pandey