

FIELD INSPECTION REPORT

Block - Dhoriya

Date of Inspection : 9/12/20	District: Banka
Division : Banka - 2	Length (km): 1.826 KM
Name of the Road: To Kadma More to Maheshpur (P.M. 984)	
Scheme/Programme: MAINTENANCE	4th Year.
Package No.: BR 0319	Road Id No.: 2070 360 21 73
Status of the Project: Ongoing/Completed/Under Maintenance	✓
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	U

(Signature)

NAME:

Saijay Kumar

DESIGNATION:

JE