

# FIELD INSPECTION REPORT

Date of Inspection : 11.12.2020		District : GAYA
Division : Neemchak Bathani		Length (Km. : 1.174
Scheme/Programme:	MAINTENANCE L 065-memphar-Gaya by P9A & Rd to Iguna	
Package No. : NA		Road Id No. : NA
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked	Remarks
<b>1 Pavement</b>		
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
<b>2 Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
<b>3 Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
<b>4 Compliance History</b>		
a)	Status of ATR's & any others.	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	SRI

11.12.2020  
J E