

FIELD INSPECTION REPORT

Date of Inspection :

Division : **Neemchak Bathani ; Sub Division - Manpur**

District : **GAYA**

Length (Km. : **0.808 Km.**

Scheme/Programme: **MMGSY (SC+Gen.) MAINTENANCE Main Road to Amri**

Package No. : **N/A**

Road Id No. : **N/A**

Status of the Project : **Under Maintenance**

Ongoing/Completed/Under Maintenance

Work is a case of : **Maintenance**

New Connectivity/Up gradation/Maintenance

Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	No Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes Yes/No
4	Compliance History	
a)	Status of ATR's & any others. No ATR. Flank requires improvement	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

[Signature]
11/12/2020.
A.E. R.W.D.
Manpur.