

FIELD INSPECTION REPORT

| | |
|---|--------------------------|
| Date of Inspection : 10-12-2020 | District: NAWADA |
| Division : RATAULI | Length (km): 1.169 KM |
| Name of the Road: AKBALPUR (DERGI AWAN) TO MANERBIHUA | |
| Scheme/Programme: MAINTENANCE | Under 5Yr 8 (PMGSY) |
| Package No.: BR-25R 649 | Road Id No.: 10502700273 |
| Status of the Project: Ongoing/Completed/Under Maintenance | |
| Work is a case of: New Connectivity/Up gradation/ Maintenance | |

| Sl. No. | Parameters to be checked | Remarks |
|---------|--|----------|
| 1. | Pavement | |
| a) | Road Junction condition | S/U ✓ |
| b) | Condition of Surfacing | S/U ✓ |
| c) | Riding Quality | S/U ✓ |
| d) | Road Camber | ✓S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | ✓Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | ✓Yes/No |
| g) | Compaction of flank/slope & raincuts if any | Yes/No |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | ✓S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓Yes/No |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | |

Overall Rating :

| | |
|---|-----|
| Satisfactory (S) | |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | "U" |

[Signature]
10-12-2020
(Signature)

NAME: SUMAN-KUMAR
DESIGNATION: ASSISTANT-ENGINEER