

FIELD INSPECTION REPORT

Date of Inspection : 10-12-2020	District: NAWADA
Division : RAJAWLI	Length (km): 1.539 km
Name of the Road: PAKRI T03 TO KULNA (PMGSY)	
Scheme/Programme: MAINTENANCE	Under 5 Yrs (PMGSY)
Package No.: BR-25R-234	Road Id No.: 10502702096
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No✓
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	"U"

[Signature]
10-12-2020
(Signature)

NAME: ASSISTANT SUMAN-KUMAR

DESIGNATION: ASSISTANT ENGINEER