

# FIELD INSPECTION REPORT

Date of Inspection :	10/12/2020	District:	NAWADA
Division :	Rajauli	Length (km):	0.600 KM
Name of the Road:	Jayuli PINGRY ROAD to Jalalpur west tola		
Scheme/Programme:	MAINTENANCE		GT & NY
Package No.:	N/A	Road Id No.:	10502718002
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
<b>1.</b>	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
<b>2.</b>	<b>Gross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
<b>3.</b>	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
<b>4.</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	N A

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

*Binod*  
10.12.2020  
(Signature)

NAME: BINOD KUMAR  
DESIGNATION: JUNIOR ENGINEER