FIELD INSPECTION REPORT

nspection: \	0/12/2020	District: Naw	Jada
Division: Rajauli		Length (km):	1350
the Road: 3	result PM64Y	road to Bighap	at Mahanamah
Programme:	MAINTENANCE	GTSNY	
No.:	N/A	. /	2718005
of the Project: Ongoing/Completed/Under Maintenance			
n case of: New Connectivity/Up gradation/ Maintenance			
1	Parameters to	be checked	Remarks
Pavement			/
֡	the Road: Derogramme: No.: The Project: n case of:	the Road: Track PM44Y Programme: MAINTENANCE No.: N/A The Project: Ongoing/Completed a case of: New Connectivity/C Parameters to	: Rajacta Length (km): O the Road: Describ PMAY road to Bistop Programme: MAINTENANCE / GTSNY No.: N/A Road Id No.: 1056 The Project: Ongoing/Completed/Under Maintenance n case of: New Connectivity/Up gradation/ Maintenance Parameters to be checked

SI. No.	Parameters to be checked	Remarks	
1. 1	Pavement	/	
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	, S\(T\)	
d)	Road Camber	S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
Ŋ	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & mincuts if any	Yes/No	
12.00	Gross Drainage	1/33	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	7.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
A PA	Compliance History	1	
a)	Status of ATR's & any others	NA	

Overall Rating

Satisfactory (S)	5"
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	

(Signature)

NAME:

SINOD KUMAR

DESIGNATION:

JUNIOR ENGINEER