

FIELD INSPECTION REPORT

Date of Inspection :- 11/12/2020	District:- Buxar
Division :- Buxar	Length (km): 4.75 km.
Name of the Road:- Pasahara Kapti Path road to Buxar Dumraon road/via Dharam Pur, Pandit Pur Basauli road.	
Scheme/Programme: MAINTENANCE	
Package No.:- MR- N/19-20 Buxar/21	Road Id No.:
Status of the Project: ☒ Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U/N.A
b)	Condition of Surfacing	S/U/N.A
c)	Riding Quality	S/U/N.A
d)	Road Camber	S/U/N.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No/N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No/N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U/N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U/N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U/N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No ☒
4.	Compliance History :- Work is in progress.	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S) ☒	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	