

FIELD INSPECTION REPORT

Date of Inspection :		District: <u>East Champaran</u>
Division : <u>Barh</u>		Length (km): <u>2.170</u>
Name of the Road: <u>Barh - Champaran Bypass</u>		
Scheme/Programme: <u>MAINTENANCE</u>		
Package No.: <u>MA-N/19-20 Barh-97</u>	Road Id No.: <u>317831034320</u>	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	No Yes/No
g)	Compaction of flank/slope & raincuts if any	No Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) [Signature] 11.11.2020

NAME: Shari Banskari

DESIGNATION: Ex. ER.
A.W.D. W.D.
Barh

Scanned with CamScanner