

FIELD INSPECTION REPORT

Date of Inspection :	District: <u>Munger</u>
Division : <u>Mungr</u>	Length (km): <u>0.722</u>
Name of the Road: <u>Shampun Bageshwari main road to Mandal dola & Sak</u>	
Scheme/Programme: <u>MAINTENANCE</u>	<u>to La via Tandi to La</u>
Package No.:	Road Id No.: <u>2090 3708009</u>
Status of the Project:	Ongoing/Completed/Under Maintenance <u>(25.03.12)</u>
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

out of Maintenance

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

M. K. Mandal
11.12.20
(Signature)

NAME: