FIELD INSPECTION REPORT

		FIELDINGLE	C I I C I C I C I C I C I C I C I C I C	
Date of Inspection: 3/12/2020			District: Mung-er_	
			1 - math (km): 1:\CO	
Division: Munter Name of the Road: NH 80 @ Se Singlethw			ma Tola hote have Sitakunddih	Catiyo Tak
Name o	f the Road: NH	80 Be Se Singles	MK >054	
Scheme/Programme: MAINTENANCE			Road Id No.: 20 80 37 0 81+3	
Package No.:				
Status of the Project: Ongoing/Complete		Ongoing/Complete	d/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance Remarks		
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement			OF TOTAL WIFE PAR
a)	Road Junction condition			LS/U .
b)	Condition of Surfacing			∠S/U
c)	Riding Quality			JS/U
d)	Road Camber			_S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U N
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a) ,	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No

Overall Rating

4.

a)

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Signature)

Nσ

NAME: fam Dered sight

Compliance History

Status of ATR's & any others

Scanned with CamScanner