FIELD INSPECTION REPORT

	fInspection: C	7-12-2020 Dis	trict: LAKHISARAI	
DIVISION: LAKUICADAT			Length (km): 0.811 Km	
	of the Road:	TIO DOGAL MAINTENANCE		
-	e/Programme:	** ** ** ** ** ** ** ** ** ** ** ** **		***************************************
Packag			d ld No.:	
Status of the Project: O Work is a case of: N		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
SI No.		New Connectivity/Up grad	dation/ Maintenance	
		Parameters to be ell	ecked	Remar
11	Pavement			
a)	Road Junction condition			2/1
b)	Condition of Surfacing			S/U
c)	Riding Quality			SAU
				、S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
D)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Eross identifat	o		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			
3.	Road Rurniture S/SR/U			3/3/5/0
.a) ç	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
		sib iy (L. 7) (1)		
a)	Status of ATR's	& any others		200

Overall Rating

Satisfactory (S)	***************
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

07/12/2020 (Signature)

NAME