## FIELD INSPECTION REPORT

Date	of Inspection :	09.12 2020	District: Jamui	
Division: R.W.D. DIV. Thayla Length (km): 4.31 KM				1
Name	of the Road: A	gahra To Sabo	sipore	-1.4
	ne/Programme:	MAINTENANCE	MEWOOXICENT. MR	
		1 + HA 19 10007	Road Id No.: 208041024	234
- 11 Contract - 1	of the Project:	New Connectivity/H	/Under Maintenance Road To	msferred T
SI. No		Parameters to	The second secon	Remarks
	Castly on this is a	Thrameters to	be cheeked	Kemaiks
1.0	THE PERSON NAMED IN STREET			1. 4. 30 4. 2
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			s/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage	wast sold a		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture	Road Furniture		
a)		•	utionary Board/km & 200m ovided and maintained	Yes/No
<b>4.</b>	Compliance His	tory	人们是这一批企业企业。当	
a)	Status of ATR's	& any others		

Overall Rating

Satisfactory (S)	NA	
Satisfactory but requires Improvement (SRI)	-	
Unsatisfactory (U)		

Lord frangement to RCD

Aug 112/2020

(Signature)

NAME:

DESIGNATION: