

FIELD INSPECTION REPORT

Date of Inspection : 11/12/2020	District: Pune
Division : Baisi	Length (km): 4.25
Name of the Road: Nawabganj to Chabanghat	
Scheme/Programme: MAINTENANCE	
Package No.: MR-N/19-20 Baisi/17	Road Id No.:
Status of the Project:	Ongoing ☒ Completed ☐ Under Maintenance ☐
Work is a case of:	New Connectivity ☐ Up gradation ☒ Maintenance ☐

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A.
g)	Compaction of flank slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	☒ S/SRI/U
c)	Condition of railings/slab approach for Bridges	S/SRI/U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	☒ Yes/No
4.	Compliance History	
a)	Status of AIR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
(Signature) 11/12/2020

NAME: Rakesh Kumar

DESIGNATION: A.E.