Date of	Inspection: 12/12/20 District: Muzaton	bur	
Division	11: Muzatorpour East -) Length (len)		
Name o	of the Road: Etwaskus chank NH-57 to Bo	hen	nbu pmire
centine	or regramme: MAINTENANCE		
Package	1 1 1000 10 170.		
	of the Project: Ongoing/Completed/Under Maintenance of New Connectivity/Un gradation/ Maintenance	rigin	g by No
Sl. No.	The state of the s		
	The state of the s		Remarks
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing	M	A S/U
c)	Riding Quality	NIV	S/U
d)	Road Camber	A	A S/U
c)	Whether free from defects such as visible cracks, expaggregates in case of CC Pavement.	posed	Yes/No
f)	Contraction Joints provided or not (CC Pavement) Yes/No		
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage	-//	
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U)		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U M
c)	Condition of railings/slab/approach for Bridges	-	S/SRI/U/
3.	Road Furniture		B/BIG/T
a)	Whether sign boards/informatory/cautionary Board/km & 3 stones/Pavement road markings are provided and maintained	200m	Yes/No //
4.	Compliance History		- 1
a)	Status of ATR's & any others		
Overall R	Rating		
	Satisfactory (S)		

Satisfactory (S)	7
Satisfactory but requires Improvement (SRI)	- 1
Unsatisfactory (U)	

NAME: Santosh kumar Pankaj DESIGNATION: Tunior Engineer

(Signature) 12/12/202