

FIELD INSPECTION REPORT

Date of Inspection : 12.12.2020	District: East Champaran
Division : Motihari	Length (km):
Name of the Road: In Sitalpur Dhala Jatawa Javerwa Road from Bigna to M.	
Scheme/Programme:	MAINTENANCE (old)
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NA

There are no provision for maintenance in above Maint. Road. Presently This alignment under const. Road named- Sitalpur Dhala to Jatawa Javerwa Road-6.50km under MR 3054 old.

[Signature]
12/12/2020
(Signature)

NAME: Baidyanath Kumar

DESIGNATION: J.E.