## FIELD INSPECTION REPORT

Division: Green Length (km): 1/7			District: Gust champered	
			Length (km): 317	
Name	of the Road: 🌬	pairing of ro	all from kamal pipm 1	to between
Schem	e/Programme:	MAINTENANCE		
Administratives (Management of	ge No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
SI. No.		Parameters for	be checked	Remarks
1.	Pavement	5.7. Take 2.187.3.20	Mercula Manufactural Estate Control of the Control	
a)	Road Junction condition MTS		S/U	
b)	Condition of Surfacing			S/U
c)	Riding Quality  Road Camber			S/U
d)	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)				Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SR			S/SRI/U
		tion of Abutment & Wing walls, Slab in RCC culverts		
		ings/slab/approach for Bridges S/SF		
	Road Furniture			
	Whether sign b tones/Pavement	oards/informatory/cautionary Board/km & 200m road markings are provided and maintained Yes/No		
C	ompliance His	ory		Same Sugar
S	tatus of ATR's &	& any others		

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

(Signature)

NAME: Shri prakash

DESIGNATION: E-E.

R.W. D. Areraj

Scanned with CamScanner