

FIELD INSPECTION REPORT

Date of Inspection :	12/12/2020	District:	East Champaran
Division :	Pakri dayal	Length (km):	0.370 Km
Name of the Road:	Repair of Road from Bokane Bank to Pined Narayan Singh house		
Scheme/Programme:	MAINTENANCE	NR-3054	OLD
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance out of maintenance		
Work is a case of:	New Connectivity/Up-gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
	Compliances History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note - out of 5 years maintenance.

(Signature)

12/12/20
at