

FIELD INSPECTION REPORT

Date of Inspection: 02/12/2020

District: Nalanda

Division: Nalanda

Length (km):

Name of the Road: Lal Se Bhadaul Road progress

Scheme Programme: MAINTENANCE

Package No.:

Road Id No.:

Status of the Project: Ongoing/Completed/Under Maintenance

Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/RI
b)	Condition of Surfacing	S/RI
c)	Riding Quality	S/RI
d)	Road Camber	S/RI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
5.	Status of ATR's & any others	

N/A

Overall Rating :

Satisfactory (S)

Satisfactory but requires improvement (SRI)

Unsatisfactory (U)

→ Road is in under PMGSY Phase II in progress

This Road is progress under PMGSY II

Taran Kumar

Taran Kumar
(Signature)