

FIELD INSPECTION REPORT

Date of Inspection:	05.12.2020	District:	Maharashtra
Division:	Hill &	Length (km):	1.282
Name of the Road:	M. N. V. J. S. N. P. N. D.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Surface condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregation in case of CC Pavement.	Yes/No 4/4
f)	Construction Joints provided or not (CC Pavement)	Yes/No 4/4
g)	Compaction of flank/slope & rainwater if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its pointing	S/SRL ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRL ✓
c)	Condition of railings/side approach for Bridges	S/SRL ✓
3.	Road Furniture	
a)	Whether sign boards/informative/cautionary Board/lan & 200m ahead Pavement road markings are provided and maintained.	Yes/No 4/4
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

1

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	U

Inspector's Name

05.12.2020
(Signature)