FIELDANSPECTION REPORT

	FIELD TRANSPORKET OKT	
	Inspection: 03/12/20 District: PATNA	
Division: DANAPUR Length (km): 2.10		
Name of the Road: Suroumana - Bibto Road		
Scheme/Programme: MAINTENANCE		
Packag		
	of the Project: Ongoing/Completed/Under Maintenance	
130 6 V20	s a case of: New Connect vity/Up gradation/ Maintenance	Marin Orași de Soura I velit
SI No.	Las Darameio, sio be checked	Remarks
10	Payenence Research	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2:57	GrossiDrainage: 10.00 part of the control of the co	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b) ·	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Rumiture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
	Compliance Pitsiory 13, 14 and 15	
a)	Status of ATR's & any others	
L	1900 not Clarifal	

Overall Rating

Work not Started.

Satisfactory but requires Improvement (SRI)

J.E. Bilta Anil Kumar

03/12/20 A. E. IR.W.D.

Unsatisfactory (U)

Satisfactory (S)

(Signature)

NAME:

DESIGNATION: