

FIELD INSPECTION REPORT

Date of Inspection :- 11/12/2020	District :-	Buxar
Division :- Buxar	Length (km):	1.15 km / 2.10 km.
Name of the Road :- Buxar Mathia Mohalla to Ahirauli		
Scheme/Programme:	MAINTENANCE	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U/ N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U/ N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U/ N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI) ✓	S.R.I.
Unsatisfactory (U)	

NAME:

(Signature)

11.12.20