

FIELD INSPECTION REPORT

Date of Inspection :	09/12/2020	District:	Munger
Division :	Munger	Length (km):	0.270
Name of the Road:	Repair of road from house of Dharmendra mandal in Darigapur of Motadil Panchayat to Manshi Inda.		
Scheme/Programme:	MAINTENANCE	M/R - 2054	
Package No.:		Road Id No.:	20803708164
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No S
f)	Contraction Joints provided or not (CC Pavement)	Yes/No S
g)	Compaction of flank/slope & raincuts if any	Yes/No S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	RI Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	15m Post, 200m Post, maintenance board and signage not found.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	'SRI'
Unsatisfactory (U)	

MD-Altaf Amwar
NAME:

(Signature) 09/12/2020
JE