

FIELD INSPECTION REPORT

Date of Inspection: **12.12.2020** District: **Siwan**
 Name of the Road: **RWD Siwan-01** Length (km): **3.300 km**
 Scheme/Programme: **Chandpur Se Bhagar**
 Package No.: **Maintenance** Road Id No:

Status of the Project: **Completed** ☒ **Maintenance** ☐
 Work is a case of: **Repair/Upgradation/Maintenance**

S/L No.	Parameters to be checked	Remarks
1.	Pavement	
1	Road Junction condition	S
2	Condition of surface	S
3	Rolling Quality	S
4	Road Width	S
5	Whether free from surface water or visible cracks, exposed aggregates in case of RCC Pavement	Not provided
6	Condition of joints (in case of RCC Pavement)	NA
7	Condition of the road at the junction of the road	NA
2.	Cross Drainage	
1	Condition of the drainage system	S
2	Whether the drainage system is free from obstruction	Not provided
3	Whether the drainage system is properly maintained	NA
3.	Road Furniture	
1	Whether sign board is obligatory & clearly Board sign is 200cm cones Pavement is properly provided and maintained	yes
4.	Compliance History	
1	Status of ATR & its copies	NO ATR

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

'S'

Ravi
 10/12/2020
 JE

Sd/- **Ravindra Kumar Mandal**
 Junior Engineer